

Operational Decontamination Kit (ODK)

FG015-0005-00NA



Includes:
5x FAST-ACT 1-Kg Sorbent Bags
20x FAST-ACT Decon Mitts
20x All Hazard Wipes

AGENT TYPE: CWAs and TICs

DESIGN FOR: Decontamination and Neutralization

DECON TYPE: Operational, Emergency, Technical

SURFACE TYPES: Equipment, Hard, Skin* (mitts)

REQUIRE USERS: 2 Users

SURFACE AREA: Approximate 20-30 m²


SPILLS: Up to 12 liters**




FAST-ACT® Operational Decontamination Kit:

The kit is designed to perform operational, emergency, and/or technical decontamination on 20-30 square meters of contaminated surfaces. This could include the contaminated gear of an individual or individuals, the area in the immediate vicinity of the individual(s), and personal use equipment.


Capability of the kit will vary depending on chemical contamination density, and chemical compound.




1 Utilize the FAST-ACT® 1-Kg Sorbent Bags to apply FAST-ACT sorbent powder to contaminated surfaces for emergency decontamination of visible liquid chemical.




2 Utilize the FAST-ACT® Decon Mitts to perform emergency decontamination by following the device user manual on surfaces not to exceed 1 m² per FAST-ACT® Decon Mitt.



3 The FAST-ACT® Decon Mitt can be used to spread the powder from the sorbent bags and perform emergency decontamination of surfaces.



4 Utilize the FAST-ACT® 1-Kg Sorbent Bags to apply FAST-ACT® sorbent powder onto small chemical spills for ab-/adsorption (containment) and neutralization of visible liquid chemical.



5 Dispose of FAST-ACT® devices in accordance with local requirements.